

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 702 5TH ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 15 N	Longitude: 122 36 20 W
Township: 02S	Range: 02E	Section: 31	Block: 104
Lot: 8, 7x		Map #: 22E31AC	Tax Lot #: 7400
Date of Construction: c. 1900	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Vernacular		Plan Type/Shape: Complex	Number of Stories: 1.0
Foundation Material: Stone		Structural Framing: Unknown	Moved? No
Roof Type/Material: Cross gable / Composition shingle		Window Type/Material: Wood fixed; wood double-hung; aluminum sli	
Exterior Surface Materials Primary: Wood shingle		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: Siding, chimney, and most windows replaced; addition at southeast corner			
Number and Type of Associated Resources: Garage to south (1)			
Integrity: Fair	Condition: Good	Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input checked="" type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This one story house sits under a cross gable roof with a recessed porch at the northwest corner. The house rests on a stone foundation and is clad with wide wood shingles. The gable is supported at the porch by new steel posts with decorative steel scrollwork. The gable eaves are enclosed throughout the house, which also features a large addition at the southeast corner. The windows are primarily fixed wood sashes at the first floor level, but some double-hung wood sashes exist on the east side. The second floor windows are aluminum sliding sashes. All of the windows have narrow trim moldings. A brick chimney near the northwest corner of the house appears to have been added about 1950, constructed of Roman brick. A two car garage sits at the south end of the lot, clad with the same shingles as the house with two new roll up doors.			
Statement of Significance:			
Researcher/Organization: Alex McMurry / HPNW			Date Recorded: 3/25/2002
Survey Form Page 1	Address: 702 5TH ST	Local Designation #	SHPO #