

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 801 5TH ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 15 N	Longitude: 122 36 16 W
Township: 02S	Range: 02E	Section: 31 Block: 110 Lot: 5x, 6x	Map #: 22E31AD Tax Lot #: 11901
Date of Construction: c. 1930	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Bungalow		Plan Type/Shape: Rectangle	Number of Stories: 1.0
Foundation Material: Concrete		Structural Framing: Unknown	Moved? No
Roof Type/Material: Jerkinhead / Composition shingle		Window Type/Material: 1/1 wood double-hung; fixed	
Exterior Surface Materials Primary: Drop		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: South side windows replaced with fixed sashes			
Number and Type of Associated Resources: None			
Integrity: Good	Condition: Good	Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input checked="" type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This one story house sits under a side gable roof that is clipped and features enclosed eaves and gable end returns. A small gable projects out from the center of the south façade over the main entry to the house, supported by a pair of large brackets. This small gable features boxed eaves and an arched ceiling over the entry. The house is clad with drop siding finished with cornerboards above the poured concrete foundation. The windows are primarily 1/1 double-hung wood sash, but the south side windows have been replaced with fixed sashes. The windows typically feature wide board trim on all four sides. A brick chimney is located on the west wall of the house.			
Statement of Significance:			

Researcher/Organization: Alex McMurry / HPNW		Date Recorded: 3/25/2002	
Survey Form Page 1	Address: 801 5TH ST	Local Designation #	SHPO #