

## OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: <b>806 5TH ST</b>		City: <b>OREGON CITY</b>	
USGS Quad Name: <b>Oregon City</b>		GPS Latitude: <b>45 21 13 N</b>	Longitude: <b>122 36 17 W</b>
Township: <b>02S</b>	Range: <b>02E</b>	Section: <b>31</b> Block: <b>109</b> Lot: <b>7x, 8x</b>	Map #: <b>22E31AD</b> Tax Lot #: <b>12900</b>
Date of Construction: <b>c. 1925</b>	Historic Name:	Historic Use or Function: <b>Domestic - single dwelling</b>	
Grouping or Cluster Name: <b>NA</b>	*Current Name or Use: <b>Domestic - single dwelling</b>	Associated Archaeological Site: <b>Unknown</b>	
Architectural Classification(s): <b>Bungalow</b>		Plan Type/Shape: <b>Rectangle</b>	Number of Stories: <b>1.0</b>
Foundation Material: <b>Concrete</b>		Structural Framing: <b>Unknown</b>	Moved? <b>No</b>
Roof Type/Material: <b>Jerkinhead / Composition shingle</b>		Window Type/Material: <b>1/1 wood double-hung; fixed</b>	
Exterior Surface Materials Primary: <b>Lap</b>		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: <b>North side windows replaced with fixed sashes</b>			
Number and Type of Associated Resources: <b>None</b>			
Integrity: <b>Good</b>	Condition: <b>Good</b>	Local Ranking:	National Register Listed? <b>No</b>
Potentially Eligible: <input type="checkbox"/> Individually or <input checked="" type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This bungalow sits under a side clipped gable with a projecting gable on the north side over the front porch. The porch gable is supported by paired Doric columns beneath a wide frieze and features a barrel vault ceiling over the entrance to the house. The main gable features open eaves, knee brackets, and wide barge boards, all typical of the style. The house is entirely clad with horizontal lap siding, finished with cornerboards. The windows are primarily 1/1 double-hung wood sash with wide board trim that features decorative edge molding. The north side windows have been replaced with fixed sashes but retain their original trim. A brick chimney is located on the east wall of the house, and has a recent galvanized cap. A cut stone retaining wall lines the property on the north side.			
Statement of Significance:			
Researcher/Organization: <b>Alex McMurry / HPNW</b>			Date Recorded: <b>3/25/2002</b>
<b>Survey Form Page 1</b>	Address: <b>806 5TH ST</b>	Local Designation #	SHPO #