

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 904 5TH ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 12 N	Longitude: 122 36 14 W
Township: 02S	Range: 02E	Section: 31 Block: 132 Lot: 7x, 8x	Map #: 22E31DA Tax Lot #: 4100
Date of Construction: c. 1950	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Minimal Tract		Plan Type/Shape: L-shaped	Number of Stories: 1.0
Foundation Material: Concrete		Structural Framing: Unknown	Moved? No
Roof Type/Material: Hip / Composition shingle		Window Type/Material: 1/1 wood double-hung; fixed	
Exterior Surface Materials Primary: Wood shingle		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: Garage door replaced			
Number and Type of Associated Resources: None			
Integrity: Good Condition: Good		Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input checked="" type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This modest house sits under a hip roof with a second hip extending to the north over a large rectangular bay. The entry porch is recessed under this second hip on the east side of the bay, where the eave is supported by a single square post. The hip eaves are all enclosed above the wood shingle siding on the main body of the house. The windows are primarily 1/1 double-hung wood sash, but the north side windows are large fixed sashes. The windows typically feature decorative trim molding throughout the house. Beneath the rectangular bay, a one car garage is present at the basement level. This garage has a new roll up door, and the driveway is framed by a concrete retaining wall on the east side and a concrete block wall on the west. The north side of the lot has a low concrete retaining wall and a large concrete stair leading up to the house.			
Statement of Significance:			
Researcher/Organization: Alex McMurry / HPNW			Date Recorded: 3/25/2002
Survey Form Page 1	Address: 904 5TH ST	Local Designation #	SHPO #