

## OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: <b>917 5TH ST</b>		City: <b>OREGON CITY</b>	
USGS Quad Name: <b>Oregon City</b>		GPS Latitude: <b>45 21 12 N</b>	Longitude: <b>122 36 12 W</b>
Township: <b>02S</b>	Range: <b>02E</b>	Section: <b>31</b> Block: <b>131</b> Lot: <b>4x, 3x</b>	Map #: <b>22E31AD</b> Tax Lot #: <b>14600</b>
Date of Construction: <b>c. 1922</b>	Historic Name:	Historic Use or Function: <b>Domestic - single dwelling</b>	
Grouping or Cluster Name: <b>NA</b>	*Current Name or Use: <b>Domestic - single dwelling</b>	Associated Archaeological Site: <b>Unknown</b>	
Architectural Classification(s): <b>Bungalow</b>		Plan Type/Shape: <b>Rectangle</b>	Number of Stories: <b>1.0</b>
Foundation Material: <b>Concrete</b>		Structural Framing: <b>Unknown</b>	Moved? <b>No</b>
Roof Type/Material: <b>Gable / Composition shingle</b>		Window Type/Material: <b>1/1 wood double-hung</b>	
Exterior Surface Materials Primary: <b>Lap</b>		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: <b>Entry stair railings added</b>			
Number and Type of Associated Resources: <b>None</b>			
Integrity: <b>Excellent</b> Condition: <b>Good</b>		Local Ranking:	National Register Listed? <b>No</b>
Potentially Eligible: <input type="checkbox"/> Individually or <input checked="" type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This one story house sits under a side gable roof with a second gable projecting out from the south side of the house to cover the front porch. The gables feature boxed eaves and narrow rake boards. The porch gable is supported by a pair of tapered square columns set on a solid balustrade that encircles the porch. The porch balustrade, like the rest of the house, is clad with narrow beveled lap siding. The house rests on a poured concrete foundation, and all of the windows are 1/1 wood double-hung sashes. The windows typically feature wide board trim on three sides with narrow sills and small apron moldings. The house retains an excellent level of integrity, and is a symmetrical composition.			
Statement of Significance:			

Researcher/Organization: <b>Alex McMurry / HPNW</b>		Date Recorded: <b>3/25/2002</b>	
<b>Survey Form Page 1</b>	Address: <b>917 5TH ST</b>	Local Designation #	SHPO #