

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 903 6TH ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 16 N	Longitude: 122 36 10 W
Township: 02S	Range: 02E	Section: 31 Block: 130 Lot: 5x, 6x	Map #: 22E31AD Tax Lot #: 9800
Date of Construction: c. 1922	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Bungalow		Plan Type/Shape: Complex	Number of Stories: 1.0
Foundation Material: Concrete		Structural Framing: Unknown	Moved? No
Roof Type/Material: Cross gable / Composition shingle		Window Type/Material: Wood fixed; vinyl sliders	
Exterior Surface Materials Primary: Wood shingle		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: Most windows replaced; siding replaced; deck added over garage			
Number and Type of Associated Resources: None			
Integrity: Good	Condition: Good	Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input checked="" type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This 1-1/2 story house sits under a cross gable roof with a large gable on the south side of the house over the enclosed entry porch. The gables typically feature open eaves with knee brackets that penetrate the wide barge boards. The house is clad with wood shingles, and features an attached garage at the southeast corner. This garage has a flat roof that is covered by a wood deck accessed through the enclosed porch. The windows in the house are primarily vinyl sliding sashes, with some fixed and double-hung windows as well. The windows typically feature narrow trim molding. The house features two gables on the west side and a small cantilevered rectangular bay near the south end of the west façade.			
Statement of Significance:			
Researcher/Organization: Alex McMurry / HPNW			Date Recorded: 3/25/2002
Survey Form Page 1	Address: 903 6TH ST	Local Designation #	SHPO #