

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 910 6TH ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 15 N	Longitude: 122 36 11 W
Township: 02S	Range: 02E	Section: 31 Block: 131 Lot: 7x, 8x	Map #: 22E31AD Tax Lot #: 14000
Date of Construction: c. 1935	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Minimal Tract		Plan Type/Shape: Rectangle	Number of Stories: 1.5
Foundation Material: Concrete		Structural Framing: Unknown	Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: 4/4 double-hung; 8-pane casement	
Exterior Surface Materials Primary: Wood shingle		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: Porch railing added			
Number and Type of Associated Resources: Garage to SW (1)			
Integrity: Good Condition: Good		Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input checked="" type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This 1-1/2 story house sits under a front gable roof with minimal eaves. A small gable projects out from the northwest corner of the house over a rectangular bay containing the entry to the house, and a large shed dormer is present on the east side of the main gable. The house is entirely clad with wood shingles above the concrete foundation, and features decorative rake and frieze moldings. The windows are a mixture of 4/4 double-hung and eight-pane casement sashes with plain board trim. At the entry gable, an arched window is centered in the gable end and a small bull's-eye window exists just to the west of the front door. A rear entry is located on the east side of the house under a cantilevered shed roof, and a central brick chimney penetrates the ridge near the north end of the dormer. A small garage under a flat roof is located at the northeast corner of the lot.			
Statement of Significance:			
Researcher/Organization: Alex McMurry / HPNW			Date Recorded: 3/25/2002
Survey Form Page 1	Address: 910 6TH ST	Local Designation #	SHPO #