

## OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: <b>914 6TH ST</b>		City: <b>OREGON CITY</b>	
USGS Quad Name: <b>Oregon City</b>		GPS Latitude: <b>45 21 14 N</b>	Longitude: <b>122 36 11 W</b>
Township: <b>02S</b>	Range: <b>02E</b>	Section: <b>31</b> Block: <b>131</b> Lot: <b>1x, 2x</b>	Map #: <b>22E31AD</b> Tax Lot #: <b>14100</b>
Date of Construction: <b>c. 1910</b>	Historic Name:	Historic Use or Function: <b>Domestic - single dwelling</b>	
Grouping or Cluster Name: <b>NA</b>	*Current Name or Use: <b>Domestic - single dwelling</b>	Associated Archaeological Site: <b>Unknown</b>	
Architectural Classification(s): <b>Bungalow</b>		Plan Type/Shape: <b>Rectangle</b>	Number of Stories: <b>1.0</b>
Foundation Material: <b>Concrete</b>		Structural Framing: <b>Unknown</b>	Moved? <b>No</b>
Roof Type/Material: <b>Gable / Composition shingle</b>		Window Type/Material: <b>Vinyl sliders and double-hung with grid</b>	
Exterior Surface Materials Primary: <b>Vinyl</b>		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: <b>Near complete window replacement; scrollwork added in gable end</b>			
Number and Type of Associated Resources: <b>None</b>			
Integrity: <b>Fair</b> Condition: <b>Good</b>		Local Ranking:	National Register Listed? <b>No</b>
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Not 50 years old <input checked="" type="checkbox"/> Irretrievable loss of integrity			
Description of Physical and Landscape Features:			
This modest bungalow sits under a front gable roof that features enclosed eaves, a narrow frieze, and rake boards. A full width porch runs across the north façade under a hip roof supported by tapered square columns set on wood piers. A solid balustrade encircles the porch, which may be an early addition and also features a wide frieze. The house is entirely clad with vinyl siding and most windows have been replaced with trimless vinyl sliders and vinyl double-hung. The front picture window features vinyl faux divides.			
Statement of Significance:			
Researcher/Organization: <b>Alex McMurry / HPNW</b>			Date Recorded: <b>3/25/2002</b>
<b>Survey Form Page 1</b>	Address: <b>914 6TH ST</b>	Local Designation #	SHPO #