

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 1012 6TH ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 13 N	Longitude: 122 36 07 W
Township: 02S	Range: 02E	Section: 31 Block: 138 Lot: 1x	Map #: 22E31AD Tax Lot #: 15300
Date of Construction: c. 1922	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Bungalow		Plan Type/Shape: Rectangle	Number of Stories: 1.0
Foundation Material: Concrete		Structural Framing: Unknown	Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: 1/1 wood double-hung; 9/1 wood fixed	
Exterior Surface Materials Primary: Asbestos shingle		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: Siding replaced; porch railing added			
Number and Type of Associated Resources: None			
Integrity: Good Condition: Good		Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input checked="" type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This modest bungalow sits under a side gable roof with a projecting gable on the north side of the house covering the front porch. This porch gable is supported by paired square columns at the corners of the porch. All of the gables feature open eaves and wide flared barge boards. Knee brackets are present at the gable peaks, and exposed purlins are visible down the length of the rake. The house is clad with asbestos ceramic shingles and features a large brick chimney on the west wall. The windows are primarily 1/1 double-hung wood sash, but two fixed sashes flank the main entry on the north side. These sashes feature a large fixed pane topped by a nine light transom. All of the windows have narrow trim moldings. A new balustrade has been added to the porch, extending down the entry stairs.			
Statement of Significance:			
Researcher/Organization: Alex McMurry / HPNW			Date Recorded: 3/25/2002
Survey Form Page 1	Address: 1012 6TH ST	Local Designation #	SHPO #