

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 1017 6TH ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 13 N	Longitude: 122 36 06 W
Township: 02S	Range: 02E	Section: 31 Block: 139 Lot: 4x	Map #: 22E31AD Tax Lot #: 9000
Date of Construction: c. 1910	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Bungalow		Plan Type/Shape: Rectangle	Number of Stories: 1.0
Foundation Material: Concrete		Structural Framing: Unknown	Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: 1/1 wood double-hung	
Exterior Surface Materials Primary: Lap		Secondary: Drop	Decorative:
Exterior Alterations or Additions/Approximate Date: Stair railings added			
Number and Type of Associated Resources: Garage to NE (1)			
Integrity: Good Condition: Good		Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input checked="" type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This 1-1/2 story house sits under a side gable roof with a shed dormer on the south side. A recessed porch is present at the southeast corner of the house, where the main gable is supported by a large square column. The gable and shed dormer feature wide barge boards, open eaves, and knee brackets typical of the style. The house is clad with narrow lap siding above the fully developed water table, and the foundation is skirted with wide drop siding. The windows are primarily 1/1 double-hung wood sashes arranged in pairs with plain board trim. A small garage is located at the northeast corner of the lot under a flat roof and clad with drop siding.			
Statement of Significance:			
Researcher/Organization: Alex McMurry / HPNW			Date Recorded: 3/25/2002
Survey Form Page 1	Address: 1017 6TH ST	Local Designation #	SHPO #