

## OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: <b>1116 6TH ST</b>		City: <b>OREGON CITY</b>	
USGS Quad Name: <b>Oregon City</b>		GPS Latitude: <b>45 21 11 N</b>	Longitude: <b>122 36 04 W</b>
Township: <b>02S</b>	Range: <b>02E</b>	Section: <b>31</b>	Block: <b>159</b>
Lot: <b>1x, 2x</b>		Map #: <b>22E31DA</b>	Tax Lot #: <b>400</b>
Date of Construction: <b>c. 1910</b>	Historic Name:	Historic Use or Function: <b>Domestic - single dwelling</b>	
Grouping or Cluster Name: <b>NA</b>	*Current Name or Use: <b>Domestic - single dwelling</b>	Associated Archaeological Site: <b>Unknown</b>	
Architectural Classification(s): <b>Vernacular</b>		Plan Type/Shape: <b>Rectangle</b>	Number of Stories: <b>1.5</b>
Foundation Material: <b>Concrete</b>		Structural Framing: <b>Unknown</b>	Moved? <b>No</b>
Roof Type/Material: <b>Gable / Composition shingle</b>		Window Type/Material: <b>1/1 and 2/2 wood double-hung</b>	
Exterior Surface Materials Primary: <b>Drop</b>		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: <b>Porch added, c. 1925; rear wing added c. 1920; windows replaced c. 1940</b>			
Number and Type of Associated Resources: <b>None</b>			
Integrity: <b>Good</b>	Condition: <b>Good</b>	Local Ranking:	National Register Listed? <b>No</b>
Potentially Eligible: <input type="checkbox"/> Individually or <input checked="" type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This 1-1/2 story house sits under a front gable roof that features enclosed eaves above wide rake and frieze boards. A hip roofed porch wraps around the north and east sides of the house, supported by tapered square columns resting on a solid balustrade. This balustrade, like the rest of the house, is clad with horizontal drop siding finished with wide cornerboards. A one story wing extends to the south from the main body of the house under a separate gable roof. The windows in the house are a mixture of 1/1 and 2/2 double-hung wood sash with plain board surrounds. The 2/2 windows were likely added about 1940. The house rests on a high concrete foundation, and features a fully developed water table.			
Statement of Significance:			

Researcher/Organization: <b>Alex McMurry / HPNW</b>		Date Recorded: <b>3/25/2002</b>	
<b>Survey Form Page 1</b>	Address: <b>1116 6TH ST</b>	Local Designation #	SHPO #