

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 406 7TH ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 25 N	Longitude: 122 36 24 W
Township: 02S	Range: 02E	Section: 31 Block: 39	Lot: 7, 8 Map #: 22E31AB Tax Lot #: 1100
Date of Construction: c. 1920	Historic Name:	Historic Use or Function: Social - club	
Grouping or Cluster Name: NA	*Current Name or Use: Mulikin Medical Center	Associated Archaeological Site: Unknown	
Architectural Classification(s): Colonial		Plan Type/Shape: Complex	Number of Stories: 1.0
Foundation Material: Unknown		Structural Framing: Unknown	Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: 6/6 wood double-hung	
Exterior Surface Materials Primary: Brick		Secondary: Vertical groove plywo	Decorative: Lap
Exterior Alterations or Additions/Approximate Date: Accretion of buildings over time; addition to south has variegated bricks, c.1940s; addition to east had 3/3 wood double-hung windows, c.1940s			
Number and Type of Associated Resources: None			
Integrity: Good Condition: Good		Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input checked="" type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This one story Colonial has a complex plan and sits on a unknown foundation. The gable roof is covered in composition shingles. Two chimneys rise from each end of the main mass's roof. The gable ends of the main mass are topped with parapets. The rake boards of the main mass have a dentil course. The wing has eave returns on the gable end. The walls are covered with brick. Windows are primarily 6/6 wood double-hung topped with keystones. The main entrance is slightly recessed. The entry stoop is topped with a cornice supported by decorative brackets. There is a brick retaining wall.			
Statement of Significance:			

Researcher/Organization: Heather Goodson / HPNW		Date Recorded: 4/12/2002	
Survey Form Page 1	Address: 406 7TH ST	Local Designation #	SHPO #