

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 1119 7TH ST				City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 14 N		Longitude: 122 36 00 W	
Township: 02S	Range: 02E	Section: 31	Block: 157	Lot: 4x	Map #: 22E31AD Tax Lot #: 6900
Date of Construction: 1907		Historic Name: Christianson, Martin and Mabel, House		Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA		*Current Name or Use: Domestic - single dwelling		Associated Archaeological Site: Unknown	
Architectural Classification(s): Vernacular			Plan Type/Shape: Rectangle		Number of Stories: 1.5
Foundation Material: Concrete			Structural Framing: Unknown		Moved? Yes
Roof Type/Material: Gable / Composition shingle			Window Type/Material: 1/1 wood double-hung		
Exterior Surface Materials Primary: Drop		Secondary: Lap		Decorative: Wood shingle	
Exterior Alterations or Additions/Approximate Date: Front porch c.1920; hip porch at rear c.1920; west wing c.1930					
Number and Type of Associated Resources: None					
Integrity: Good		Condition: Good		Local Ranking: Designated Historic Site	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input checked="" type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old					
Description of Physical and Landscape Features:					
This 1-1/2 story house sits under a front gable roof facing 7th Street. A number of hipped one-story additions have been made over the years to the house. On the rear is an addition c.1920. To the west is an addition c.1930. An infill of the corner porch on the east side was made c.1930. The front porch has been rebuilt with a lap siding rail and 4"x4" posts. The gable roof of the main house features eave brackets, exposed rafter tails and a barge board. There is wood imbrication in the gable ends consisting of fish scale and square shingles. Windows are 1/1 wood double hung with lamb's tongues on the main body of the house, with additions having the same without the lamb's tongues. The building sits on a board-formed concrete foundation with the west addition on concrete block. The house has had numerous additions over the years, however, most are over 50 years of age.					
Statement of Significance:					
The first known residents of 1119 7th Street were Mr. and Mrs. Christianson. Mr. Christianson worked for the City.					

Researcher/Organization: Bernadette Niederer / HPNW			Date Recorded: 4/6/2002		
Survey Form Page 1	Address: 1119 7TH ST		Local Designation #		SHPO #