

## OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: <b>1306 7TH ST</b>		City: <b>OREGON CITY</b>	
USGS Quad Name: <b>Oregon City</b>		GPS Latitude: <b>45 21 11 N</b>	Longitude: <b>122 35 57 W</b>
Township: <b>02S</b>	Range: <b>02E</b>	Section: <b>31</b> Block: <b>164</b> Lot: <b>1, 2</b>	Map #: <b>22E31AD</b> Tax Lot #: <b>7000</b>
Date of Construction: <b>c. 1920</b>	Historic Name:	Historic Use or Function: <b>Domestic - single dwelling</b>	
Grouping or Cluster Name: <b>NA</b>	*Current Name or Use: <b>Hillside Chapel</b>	Associated Archaeological Site: <b>Unknown</b>	

Architectural Classification(s): <b>International</b>	Plan Type/Shape: <b>Rectangle</b>	Number of Stories: <b>1.0</b>
Foundation Material: <b>Concrete</b>	Structural Framing: <b>Unknown</b>	Moved? <b>No</b>
Roof Type/Material: <b>Flat / Built-up</b>	Window Type/Material: <b>Large fixed pane; Ribbon sliding</b>	
Exterior Surface Materials Primary: <b>Stucco</b>	Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: <b>None apparent</b>		
Number and Type of Associated Resources: <b>1-1/2 story English Cottage to rear; free standing carport to west (2)</b>		

Integrity: <b>Excellent</b>	Condition: <b>Good</b>	Local Ranking:	National Register Listed? <b>No</b>
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input checked="" type="checkbox"/> Not 50 years old			

Description of Physical and Landscape Features:

This one story International style building, built into a hill, has a rectangular plan and sits on a poured concrete foundation. The flat roof is built-up. The walls are covered with stucco. Windows are primarily large fixed-pane with color and ribbon sliding windows. The main entrance is recessed and covered with a metal awning. Brick planters flank the main entrance. A stone retaining wall is adjacent to the west façade.

To the rear of the mortuary is a 1-1/2 story c.1930 English Cottage, undoubtedly where the Hillside Chapel got started. It is detached from the International style building, but does not appear to be within the conservation district's boundaries. A free-standing carport is within the boundaries and on the tax lot. Windows are 6/1 wood double-hung, and fixed wood sash flanked by 4/1 wood double-hung. The walls are covered with stucco. The jerkinhead roof has rounded eaves and is clad in wood shingles. There is an arched entry porch.

Statement of Significance:

---

Researcher/Organization: <b>Heather Goodson / HPNW</b>	Date Recorded: <b>4/6/2002</b>
<b>Survey Form Page 1</b> Address: <b>1306 7TH ST</b>	Local Designation # SHPO #