

## OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: <b>905 8TH ST</b>		City: <b>OREGON CITY</b>	
USGS Quad Name: <b>Oregon City</b>		GPS Latitude: <b>45 21 21 N</b>	Longitude: <b>122 36 05 W</b>
Township: <b>02S</b>	Range: <b>02E</b>	Section: <b>31</b> Block: <b>128</b> Lot: <b>5x</b>	Map #: <b>22E31AD</b> Tax Lot #: <b>1700</b>
Date of Construction: <b>c. 1927</b>	Historic Name:	Historic Use or Function: <b>Domestic - single dwelling</b>	
Grouping or Cluster Name: <b>NA</b>	*Current Name or Use: <b>Domestic - single dwelling</b>	Associated Archaeological Site: <b>Unknown</b>	

Architectural Classification(s): <b>Bungalow</b>	Plan Type/Shape: <b>Rectangle</b>	Number of Stories: <b>1.0</b>
Foundation Material: <b>Concrete</b>	Structural Framing: <b>Unknown</b>	Moved? <b>No</b>
Roof Type/Material: <b>Cross gable / Composition shingle</b>	Window Type/Material: <b>Fixed, 1/1 double-hung</b>	
Exterior Surface Materials Primary: <b>Lap</b>	Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: <b>South window replaced</b>		
Number and Type of Associated Resources: <b>Outbuilding and garage (2)</b>		

Integrity: <b>Good</b>	Condition: <b>Good</b>	Local Ranking:	National Register Listed? <b>No</b>
Potentially Eligible: <input type="checkbox"/> Individually or <input checked="" type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			

Description of Physical and Landscape Features:

This modest house sits under a cross gable roof, with a small gable on the southwest corner over the enclosed entry. The gables feature shallow eaves with decorative rake moldings and gable end returns. The house is entirely clad with horizontal lap siding, finished with cornerboards. The windows are primarily 1/1 double-hung wood sash, but one window on the south side has been replaced with a large fixed aluminum sash with internal muntins. A brick chimney is located on the west wall of the house.

A covered walkway leads to a small outbuilding to the northwest of the main house. This building is of the same character and materials as the main house, with only a single door and small casement windows. A garage is located at the southeast corner of the lot, and also matches the composition of the house. A newer roll-up door has been added to the garage.

Statement of Significance:

---

Researcher/Organization: <b>Alex McMurry / HPNW</b>	Date Recorded: <b>3/26/2002</b>
<b>Survey Form Page 1</b> Address: <b>905 8TH ST</b>	Local Designation # SHPO #