

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 1126 8TH ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 17 N	Longitude: 122 35 59 W
Township: 02S	Range: 02E	Section: 31 Block: 157 Lot: 1	Map #: 22E31AD Tax Lot #: 6400
Date of Construction: c. 1920	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Bungalow		Plan Type/Shape: Rectangle	Number of Stories: 1.5
Foundation Material: Concrete		Structural Framing: Unknown	Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: 1/1 double-hung; casement	
Exterior Surface Materials Primary: Drop		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: Shed dormers added to east and west sides of main gable; new garage siding.			
Number and Type of Associated Resources: Garage to NW (1)			
Integrity: Good Condition: Good		Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input checked="" type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
<p>This 1-1/2 story bungalow sits under a front gable roof with large shed dormers on the east and west sides. These dormers appear to be additions to the house, but match the house in both character and materials. The main gable and dormers feature open eaves and wide barge boards, and the gable has decorative knee brackets. A full width hipped porch is present on the north side of the house, supported by tapered square columns set on a solid balustrade. This balustrade, like the rest of the house, is clad with double drop siding finished with cornerboards. The central entry door on the north side is a replacement of the original door. The windows in the house are primarily 1/1 double-hung wood sash, but the gable ends feature paired eight-pane casement windows. The windows typically feature wide board surrounds, but the casement windows have narrow trim molding. A brick chimney with a corbelled cap is centrally located in the house.</p> <p>A small garage is located just west of the house, clad with plywood with two plywood out-swinging doors.</p>			
Statement of Significance:			

Researcher/Organization: Alex McMurry / HPNW		Date Recorded: 3/26/2002	
Survey Form Page 1	Address: 1126 8TH ST	Local Designation #	SHPO #