

## OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: <b>1003 9TH ST</b>		City: <b>OREGON CITY</b>	
USGS Quad Name: <b>Oregon City</b>		GPS Latitude: <b>45 21 22 N</b>	Longitude: <b>122 35 59 W</b>
Township: <b>02S</b>	Range: <b>02E</b>	Section: <b>32</b> Block: <b>142</b> Lot: <b>5</b>	Map #: <b>22E32BC</b> Tax Lot #: <b>6100</b>
Date of Construction: <b>1938</b>	Historic Name:	Historic Use or Function: <b>Domestic - single dwelling</b>	
Grouping or Cluster Name: <b>NA</b>	*Current Name or Use: <b>Domestic - single dwelling</b>	Associated Archaeological Site: <b>Unknown</b>	
Architectural Classification(s): <b>Vernacular</b>		Plan Type/Shape: <b>Rectangle</b>	Number of Stories: <b>1.0</b>
Foundation Material: <b>Concrete</b>		Structural Framing: <b>Unknown</b>	Moved? <b>No</b>
Roof Type/Material: <b>Gable / Composition shingle</b>		Window Type/Material: <b>6/1 and 8/1 double-hung</b>	
Exterior Surface Materials Primary: <b>Lap</b>		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: <b>Partial window replacement; new siding; enclosed entry.</b>			
Number and Type of Associated Resources: <b>None</b>			
Integrity: <b>Good</b> Condition: <b>Good</b>		Local Ranking:	National Register Listed? <b>No</b>
Potentially Eligible: <input type="checkbox"/> Individually or <input checked="" type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This one story vernacular residence has a rectangular plan that sits on a concrete foundation. Its front facing gable roof is covered in composition shingles and is pierced by an interior chimney. The residence is clad in lap siding and features 8/1 and 6/1 wood double-hung windows. A gabled entry bay projects from the center of the house and appears to be an addition. Other alterations include a partial window replacement and the new siding.			
Statement of Significance:			

Researcher/Organization: <b>Sally Wright / HPNW</b>		Date Recorded: <b>9/19/2002</b>	
<b>Survey Form Page 1</b>	Address: <b>1003 9TH ST</b>	Local Designation #	SHPO #