

## OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: <b>1010 9TH ST</b>		City: <b>OREGON CITY</b>	
USGS Quad Name: <b>Oregon City</b>		GPS Latitude: <b>45 21 21 N</b>	Longitude: <b>122 36 00 W</b>
Township: <b>02S</b>	Range: <b>02E</b>	Section: <b>31</b> Block: <b>141</b> Lot: <b>8</b>	Map #: <b>22E31AD</b> Tax Lot #: <b>1100</b>
Date of Construction: <b>c. 1925</b>	Historic Name:	Historic Use or Function: <b>Other - unknown</b>	
Grouping or Cluster Name: <b>NA</b>	*Current Name or Use: <b>Religion - church hall</b>	Associated Archaeological Site: <b>Unknown</b>	
Architectural Classification(s): <b>No Style</b>		Plan Type/Shape: <b>Complex</b>	Number of Stories: <b>1.5</b>
Foundation Material: <b>Concrete</b>		Structural Framing: <b>Unknown</b>	Moved? <b>No</b>
Roof Type/Material: <b>Gable / Composition shingle</b>		Window Type/Material: <b>8/8 double-hung; aluminum sliders</b>	
Exterior Surface Materials Primary: <b>Composition shingle</b> Secondary: <b>Lap</b>		Decorative: <b>Stucco</b>	
Exterior Alterations or Additions/Approximate Date: <b>Stucco siding; wheel chair ramp and rail</b>			
Number and Type of Associated Resources: <b>None</b>			
Integrity: <b>Good</b> Condition: <b>Good</b>		Local Ranking:	National Register Listed? <b>No</b>
Potentially Eligible: <input type="checkbox"/> Individually or <input checked="" type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This building has a complex plan, resulting from the large side and rear additions. It rests on a concrete foundation and is capped by a cross gable roof of composition shingles, which is pierced by a gable roof dormer. The lower levels are sided with composition shingles, while the upper level and the gable end are clad in lap. The façade along 9th Street has been covered with stucco. Windows are primarily wood 8/8 double-hung and aluminum sliders. Decorative features include rake molding and louvered vents in the gable ends. Alterations include the rear massing, the stucco siding, and the wheel chair ramp and railing.			
Statement of Significance:			

Researcher/Organization: <b>Sally Wright / HPNW</b>		Date Recorded: <b>9/19/2002</b>	
<b>Survey Form Page 1</b>	Address: <b>1010 9TH ST</b>	Local Designation #	SHPO #