

## OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: <b>1216 9TH ST</b>		City: <b>OREGON CITY</b>	
USGS Quad Name: <b>Oregon City</b>		GPS Latitude: <b>45 21 18 N</b>	Longitude: <b>122 35 53 W</b>
Township: <b>02S</b>	Range: <b>02E</b>	Section: <b>32</b> Block: <b>166</b> Lot: <b>1x, 2x</b>	Map #: <b>22E32BC</b> Tax Lot #: <b>7900</b>
Date of Construction: <b>c. 1915</b>	Historic Name:	Historic Use or Function: <b>Domestic - single dwelling</b>	
Grouping or Cluster Name: <b>NA</b>	*Current Name or Use: <b>Domestic - single dwelling</b>	Associated Archaeological Site: <b>Unknown</b>	
Architectural Classification(s): <b>Bungalow</b>		Plan Type/Shape: <b>Square</b>	Number of Stories: <b>1.5</b>
Foundation Material: <b>Concrete</b>		Structural Framing: <b>Unknown</b>	Moved? <b>Yes</b>
Roof Type/Material: <b>Jerkinhead / Composition shingle</b>		Window Type/Material: <b>6/1 wood double-hung; 5/1 wood fixed</b>	
Exterior Surface Materials Primary: <b>Vinyl</b>		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: <b>Vinyl siding; front door; front entry hand rails; faux divides in windows; window shutters.</b>			
Number and Type of Associated Resources: <b>None</b>			
Integrity: <b>Fair</b>	Condition: <b>Good</b>	Local Ranking:	National Register Listed? <b>No</b>
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input checked="" type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This 1-1/2 story bungalow has a square plan that rests on a concrete foundation. Its front facing clipped gable, or Jerkinhead, roof is covered in composition shingles and pierced by a brick chimney stack. Exterior walls are clad in vinyl and windows are primarily 6/1 wood double-hung and 5/1 wood fixed. The half-width porch features square posts with caps on a closed rail. Characteristics of the Bungalow style include the eave brackets, the bargeboard, and the corner boards. Alterations include the replacement siding and front door, the hand rails at the entry, the shutters, and the faux divides in the upper floor windows. This house was moved to the property sometime between 1925 and 1950.			
Statement of Significance:			

Researcher/Organization: <b>Sally Wright / HPNW</b>		Date Recorded: <b>9/19/2002</b>	
<b>Survey Form Page 1</b>	Address: <b>1216 9TH ST</b>	Local Designation #	SHPO #