

## OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: <b>1220 9TH ST</b>		City: <b>OREGON CITY</b>	
USGS Quad Name: <b>Oregon City</b>		GPS Latitude: <b>45 21 17 N</b>	Longitude: <b>122 35 52 W</b>
Township: <b>02S</b>	Range: <b>02E</b>	Section: <b>32</b>	Block: <b>166</b>
Lot: <b>1x, 2x</b>		Map #: <b>22E32BC</b>	Tax Lot #: <b>8000</b>
Date of Construction: <b>c. 1925</b>	Historic Name:	Historic Use or Function: <b>Domestic - single dwelling</b>	
Grouping or Cluster Name: <b>NA</b>	*Current Name or Use: <b>Domestic - single dwelling</b>	Associated Archaeological Site: <b>Unknown</b>	
Architectural Classification(s): <b>Bungalow</b>		Plan Type/Shape: <b>Square</b>	Number of Stories: <b>1.5</b>
Foundation Material: <b>Concrete</b>		Structural Framing: <b>Unknown</b>	Moved? <b>Yes</b>
Roof Type/Material: <b>Jerkinhead / Composition shingle</b>		Window Type/Material: <b>5/1 wood fixed</b>	
Exterior Surface Materials Primary: <b>Vinyl</b>		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: <b>Vinyl siding; front hand rails; side entrance and porch; lattice skirting.</b>			
Number and Type of Associated Resources: <b>None</b>			
Integrity: <b>Fair</b>	Condition: <b>Good</b>	Local Ranking:	National Register Listed? <b>No</b>
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input checked="" type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This 1-1/2 story bungalow has square plan that rests on a concrete foundation. Its side facing jerkinhead (clipped gable) roof is covered in composition shingles and is punctured by a exterior brick chimney stack. Exterior walls are clad in vinyl and windows are primarily 5/1 wood double-hung. The half-wide porch features a jerkinhead roof and capped, square posts on a closed rail. Decorative features include the eave brackets, the bargeboard and the exposed rafter tails. Alterations include the replacement siding, the hand rails at the front entry, and the side entry porch with a shed roof and lattice skirting. This house was moved to the property sometime between 1925 and 1950.			
Statement of Significance:			

Researcher/Organization: <b>Sally Wright / HPNW</b>		Date Recorded: <b>9/19/2002</b>	
<b>Survey Form Page 1</b>	Address: <b>1220 9TH ST</b>	Local Designation #	SHPO #