

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 819 10TH ST				City: OREGON CITY			
USGS Quad Name: Oregon City			GPS Latitude: 45 21 27 N		Longitude: 122 36 01 W		
Township: 02S	Range: 02E	Section: 31	Block: 115	Lot: 3, 2x, 4x, 5x	Map #: 22E31AA	Tax Lot #: 7100	
Date of Construction: c. 1900		Historic Name: Knowles, Thomas and Bridget, Rental			Historic Use or Function: Domestic - single dwelling		
Grouping or Cluster Name: NA		*Current Name or Use: Domestic - single dwelling			Associated Archaeological Site: Unknown		
Architectural Classification(s): Vernacular				Plan Type/Shape: Complex		Number of Stories: 1.0	
Foundation Material: Concrete				Structural Framing: Unknown		Moved? No	
Roof Type/Material: Gable on hip / Composition shingle				Window Type/Material: 6/1 wood double-hung; fixed			
Exterior Surface Materials Primary: Wood shingle				Secondary:		Decorative:	
Exterior Alterations or Additions/Approximate Date: More alterations than original materials; however, additions over 50 years old.							
Number and Type of Associated Resources: None							
Integrity: Fair		Condition: Good		Local Ranking: Designated Historic Site		National Register Listed? No	
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input checked="" type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old							
Description of Physical and Landscape Features:							
The house has gone many alterations since its pre-1900 construction date. The only portion of the building from the exterior that belies its age is the tall gabled roof at its center mass. Sanborns reveal the south projection to be original to the house with infill of its porches occurring on its south and east sides c.1925. A garage was added to its northeast corner c.1930. The arched entry is also c.1930. The house is clad in wood shingles that were probably part of a c.1950 remodel. The gable roof has minimal eave returns.							
Statement of Significance:							
This residence appears to have been constructed during the ownership of Thomas and Bridge Knowles. However, they did not live in the house but instead used it as a rental.							

Researcher/Organization: David Pinyerd / HPNW				Date Recorded: 9/30/2002			
Survey Form Page 1		Address: 819 10TH ST		Local Designation #		SHPO #	