

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 1220 10TH ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 20 N	Longitude: 122 35 50 W
Township: 02S	Range: 02E	Section: 32 Block: 167 Lot: 1	Map #: 22E32BC Tax Lot #: 4200
Date of Construction: c. 1915	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Front gable and wing / Altered		Plan Type/Shape: T-shaped	Number of Stories: 2.0
Foundation Material: Concrete		Structural Framing: Unknown	Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: 1/1 wood double-hung; wood fixed	
Exterior Surface Materials Primary: Wood shingle		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: wood shingle resurfacing; windows replaced with fixed and double-hung; early shed addition to rear; porch enclosed with lattice and shingles			
Number and Type of Associated Resources: Garage to NW (1)			
Integrity: Fair	Condition: Good	Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Not 50 years old <input checked="" type="checkbox"/> Irretrievable loss of integrity			
Description of Physical and Landscape Features:			
This two story front-gable-and-wing house has a t-shaped plan. The cross gable roof is covered with composition shingles. The house is covered with wood shingles probably applied in the 1950s. Windows are primarily fixed and 1/1 double-hung. The knee wall of the shed roof entry porch is topped with lattice, enclosing most of it. There is a detached garage behind the house to the northwest.			
Statement of Significance:			

Researcher/Organization: Heather Goodson / HPNW		Date Recorded: 4/12/2002	
Survey Form Page 1	Address: 1220 10TH ST	Local Designation #	SHPO #