

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 816 11TH ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 28 N	Longitude: 122 36 00 W
Township: 02S	Range: 02E	Section: 31 Block: 115 Lot: 1, 2x	Map #: 22E31AA Tax Lot #: 7200
Date of Construction: c. 1940	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Minimal Tract		Plan Type/Shape: Rectangle	Number of Stories: 1.5
Foundation Material: Concrete		Structural Framing: Unknown	Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: 8/1 leaded double-hung; leaded fixed	
Exterior Surface Materials Primary: Wood shingle		Secondary: Brick	Decorative:
Exterior Alterations or Additions/Approximate Date:			
Number and Type of Associated Resources: Garage with carport to east (1)			
Integrity: Good Condition: Good		Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input checked="" type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This one story minimal tract house has a rectangular plan and sits on a concrete foundation with basement. The gable roof is covered with composition shingles and is pierced by two chimneys. There are shed dormers to the rear. The house is covered with wood shingle siding. Windows are primarily leaded fixed and 8/1 leaded double-hung. The gable roof entry is supported by large brick pilasters. There is an external brick chimney on west side. A double car garage is attached to the east façade and may be original to the house. There is also a detached single car garage with a carport.			
Statement of Significance:			

Researcher/Organization: Heather Goodson / HPNW		Date Recorded: 4/12/2002	
Survey Form Page 1	Address: 816 11TH ST	Local Designation #	SHPO #