

## OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: <b>1102 11TH ST</b>		City: <b>OREGON CITY</b>	
USGS Quad Name: <b>Oregon City</b>		GPS Latitude: <b>45 21 25 N</b>	Longitude: <b>122 35 52 W</b>
Township: <b>02S</b>	Range: <b>02E</b>	Section: <b>32</b>	Block: <b>154</b> Lot: <b>6x</b>
Date of Construction: <b>c. 1900</b>	Historic Name:	Historic Use or Function: <b>Domestic - single dwelling</b>	
Grouping or Cluster Name: <b>NA</b>	*Current Name or Use: <b>Domestic - single dwelling</b>	Associated Archaeological Site: <b>Unknown</b>	
Architectural Classification(s): <b>Vernacular</b>		Plan Type/Shape: <b>Complex</b>	Number of Stories: <b>1.5</b>
Foundation Material: <b>Concrete</b>		Structural Framing: <b>Unknown</b>	Moved? <b>No</b>
Roof Type/Material: <b>Gable / Composition shingle</b>		Window Type/Material: <b>1/1 wood double-hung</b>	
Exterior Surface Materials Primary: <b>Wood shingle</b>		Secondary: <b>Brick</b>	Decorative:
Exterior Alterations or Additions/Approximate Date: <b>Wood shingle siding; glass block</b>			
Number and Type of Associated Resources: <b>Small, 1920s barrel roof garage to east (1)</b>			
Integrity: <b>Fair</b>	Condition: <b>Fair</b>	Local Ranking:	National Register Listed? <b>No</b>
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input checked="" type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
Located on a corner lot, this 1-1/2 story vernacular house is complex in plan and sits on a poured concrete foundation. The cross gable roof is covered in composition shingles. The house is clad in wood shingles with a belt course and topped with a wide rake board. Brick accents the front façade. Windows are primarily 1/1 wood double-hung with simple trim. The entry door, located at the intersection of the two massings, is covered by a small pent roof supported by decorative wrought iron brackets. Above the entry is a glass block window. The entry stoop has wrought iron railings. A shed roof addition is on the east façade.			
A small, 1920s barrel roof garage sits to the east of the house.			
Statement of Significance:			

Researcher/Organization: <b>Heather Goodson / HPNW</b>		Date Recorded: <b>4/12/2002</b>	
<b>Survey Form Page 1</b>	Address: <b>1102 11TH ST</b>	Local Designation #	SHPO #