

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 302 BLUFF ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 16 N	Longitude: 122 36 37 W
Township: 02S	Range: 02E	Section: 31 Block: 310 Lot: 4x	Map #: 22E31AC Tax Lot #: 12400
Date of Construction: c. 1910	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Bungalow		Plan Type/Shape: Rectangle	Number of Stories: 1.0
Foundation Material: Unknown		Structural Framing: Unknown	Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: 1/1 wood double-hung; vinyl	
Exterior Surface Materials Primary: Asbestos shingle		Secondary: Lap	Decorative:
Exterior Alterations or Additions/Approximate Date: Siding replaced, most windows replaced, entry stairs rebuilt.			
Number and Type of Associated Resources: None			
Integrity: Good Condition: Good		Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input checked="" type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This modest house sits under a front gable roof with a hipped porch running nearly the full width of the west façade. The porch hip is supported by a series of turned columns with a new wood balustrade encircling the porch. This balustrade matches the recently replaced entry stair balustrades. The house is clad with asbestos ceramic shingles, and features shallow enclosed eaves. The original windows visible on the west façade are 1/1 double-hung wood sash with wide board trim, but most of the windows have been replaced with vinyl double-hung or sliding sashes. These replacement windows have no exterior trim. The basement level features a number of double-hung sashes, and is clad with lap siding.			
Statement of Significance:			
Researcher/Organization: Alex McMurry / HPNW			Date Recorded: 3/25/2002
Survey Form Page 1	Address: 302 BLUFF ST	Local Designation #	SHPO #