

## OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: <b>201 CENTER ST</b>		City: <b>OREGON CITY</b>	
USGS Quad Name: <b>Oregon City</b>		GPS Latitude: <b>45 21 12 N</b>	Longitude: <b>122 36 35 W</b>
Township: <b>02S</b>	Range: <b>02E</b>	Section: <b>31</b> Block: <b>35</b> Lot: <b>4x</b>	Map #: <b>22E31AC</b> Tax Lot #: <b>13500</b>
Date of Construction: <b>c. 1915</b>	Historic Name:	Historic Use or Function: <b>Domestic - single dwelling</b>	
Grouping or Cluster Name: <b>NA</b>	*Current Name or Use: <b>Domestic - single dwelling</b>	Associated Archaeological Site: <b>Unknown</b>	
Architectural Classification(s): <b>Vernacular</b>		Plan Type/Shape: <b>Rectangle</b>	Number of Stories: <b>1.0</b>
Foundation Material: <b>Concrete</b>		Structural Framing: <b>Unknown</b>	Moved? <b>No</b>
Roof Type/Material: <b>Hip / Composition shingle</b>		Window Type/Material: <b>1/1 wood double-hung; vinyl sliders; vinyl do</b>	
Exterior Surface Materials Primary: <b>Asbestos shingle</b>		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: <b>Asbestos shingles; vinyl sliders and double-hung windows in dormers.</b>			
Number and Type of Associated Resources: <b>None</b>			
Integrity: <b>Good</b> Condition: <b>Good</b>		Local Ranking:	National Register Listed? <b>No</b>
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input checked="" type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			IMAGE UNAVAILABLE SEE ORIGINAL SURVEY FORM FOR PHOTOGRAPH
Description of Physical and Landscape Features:			
This one story transitional-style house has a rectangular plan and sits on a poured concrete foundation. The hip roof is covered in composition shingles and is pierced by two hip dormers. Rafter tails are exposed though obscured by gutters. The house is covered in asbestos ceramic shingles grounded by a water table. Windows are primarily 1/1 wood double-hung with hood molding and sill. There are vinyl double-hung and sliders in the dormers. There is a small corner inset porch. House duplicate of 205 Center Street.			
Statement of Significance:			
Researcher/Organization: <b>Heather Goodson / HPNW</b>			Date Recorded: <b>4/6/2002</b>
<b>Survey Form Page 1</b>	Address: <b>201 CENTER ST</b>	Local Designation #	SHPO #