

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 206 CENTER ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 12 N	Longitude: 122 36 34 W
Township: 02S	Range: 02E	Section: 31 Block: 58	Lot: 5, 6x Map #: 22E31AC Tax Lot #: 13600
Date of Construction: c. 1900	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Vernacular / Classical Revival		Plan Type/Shape: Rectangle	Number of Stories: 1.5
Foundation Material: Concrete		Structural Framing: Unknown	Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: 1/1 wood double-hung	
Exterior Surface Materials Primary: Asbestos shingle		Secondary: Wood shingle	Decorative:
Exterior Alterations or Additions/Approximate Date: Porch rebuilt, c.1990s Early one-story, hipped roof addition to rear.			
Number and Type of Associated Resources: None			
Integrity: Fair	Condition: Good	Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input checked="" type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			IMAGE UNAVAILABLE SEE ORIGINAL SURVEY FORM FOR PHOTOGRAPH
Description of Physical and Landscape Features:			
This 1-1/2 vernacular house has a rectangular plan and sits on a poured concrete foundation. The gable roof is covered in composition shingles with eave returns and a wide rake board. The house is covered with lap siding grounded by a water table and vertical wood skirting. Wood shingles accent the upper portion of the gable end of the front façade. Windows are primarily 1/1 wood double-hung. The hip roof entry porch is supported by narrow columns with decorative brackets at the top. There is an open railing encircling the porch.			
Statement of Significance:			
Researcher/Organization: Heather Goodson / HPNW			Date Recorded: 5/10/2002
Survey Form Page 1	Address: 206 CENTER ST	Local Designation #	SHPO #