

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 311 CENTER ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 15 N	Longitude: 122 36 32 W
Township: 02S	Range: 02E	Section: 31 Block: 36 Lot: 3	Map #: 22E31AC Tax Lot #: 11300
Date of Construction: c. 1935	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Minimal Traditional		Plan Type/Shape: Rectangle	Number of Stories: 1.0
Foundation Material: Concrete		Structural Framing: Unknown	Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: Multi-pane casement; leaded; 8/1 & 8/8 wood	
Exterior Surface Materials Primary: Wood shingle		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: None apparent			
Number and Type of Associated Resources: Period garage with original doors to the south (1)			
Integrity: Good Condition: Good		Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input checked="" type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			IMAGE UNAVAILABLE SEE ORIGINAL SURVEY FORM FOR PHOTOGRAPH
Description of Physical and Landscape Features:			
This one story minimal traditional house has a rectangular plan and sits on a poured concrete foundation. The gable roof is covered in composition shingles with wide barge boards. The house is covered in wood shingles. Windows are primarily multi-pane wood with lead casement, and 8/8 and 8/1 wood double-hung. The inset porch has wrought iron railings. There is a small shed roof side porch on the south façade. There is a brick exterior chimney on the north end. The detached garage is on the south side of the house and has its original doors.			
Statement of Significance:			
Researcher/Organization: Heather Goodson / HPNW			Date Recorded: 5/10/2002
Survey Form Page 1	Address: 311 CENTER ST	Local Designation #	SHPO #