

### OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: <b>415 CENTER ST</b>		City: <b>OREGON CITY</b>	
USGS Quad Name: <b>Oregon City</b>		GPS Latitude: <b>45 21 18 N</b>	Longitude: <b>122 36 29 W</b>
Township: <b>02S</b>	Range: <b>02E</b>	Section: <b>31</b>	Block: <b>37</b>
Lot: <b>2x</b>		Map #: <b>22E31AC</b>	Tax Lot #: <b>5900</b>
Date of Construction: <b>c. 1925</b>	Historic Name:	Historic Use or Function: <b>Domestic - single dwelling</b>	
Grouping or Cluster Name: <b>NA</b>	*Current Name or Use: <b>Domestic - single dwelling</b>	Associated Archaeological Site: <b>Unknown</b>	
Architectural Classification(s): <b>Bungalow</b>		Plan Type/Shape: <b>Rectangle</b>	Number of Stories: <b>1.0</b>
Foundation Material: <b>Concrete</b>		Structural Framing: <b>Unknown</b>	Moved? <b>No</b>
Roof Type/Material: <b>Jerkinhead / Composition shingle</b>		Window Type/Material: <b>Picture; 1/1 wood double-hung</b>	
Exterior Surface Materials Primary: <b>Lap</b>		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: <b>Blown up and burned in 2002.</b>			
Number and Type of Associated Resources: <b>Garage to west (1)</b>			
Integrity: <b>Fair</b>	Condition: <b>Poor</b>	Local Ranking:	National Register Listed? <b>No</b>
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input checked="" type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			IMAGE UNAVAILABLE SEE ORIGINAL SURVEY FORM FOR PHOTOGRAPH
Description of Physical and Landscape Features:			
This one story side-jerkinhead bungalow has a rectangular plan and sits on a poured concrete foundation. The jerkinhead roof is covered in composition shingles, has decorative eave brackets and barge board, and is pierced by two chimneys. The house is covered with narrow lap siding on the front (east) façade and wider lap siding on other facades and the gable end of the front porch. Windows are picture and 1/1 wood double-hung. The front door is flanked by two narrow multi-pane sidelights. The front porch is supported by large columns and has wrought iron railing. A side entrance on the south façade is covered by a shed roof and has an open wood railing.			
Statement of Significance:			

Researcher/Organization: <b>Heather Goodson / HPNW</b>		Date Recorded: <b>5/10/2002</b>	
<b>Survey Form Page 1</b>	Address: <b>415 CENTER ST</b>	Local Designation #	SHPO #