

## OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: <b>104 HIGH ST</b>		City: <b>OREGON CITY</b>	
USGS Quad Name: <b>Oregon City</b>		GPS Latitude: <b>45 21 10 N</b>	Longitude: <b>122 36 40 W</b>
Township: <b>02S</b>	Range: <b>02E</b>	Section: <b>31</b>	Block: <b>82</b>
Lot: <b>5x</b>		Map #: <b>22E31CA</b>	Tax Lot #: <b>700</b>
Date of Construction: <b>c. 1916</b>	Historic Name:	Historic Use or Function: <b>Domestic - single dwelling</b>	
Grouping or Cluster Name: <b>NA</b>	*Current Name or Use: <b>Domestic - single dwelling</b>	Associated Archaeological Site: <b>Unknown</b>	
Architectural Classification(s): <b>Bungalow</b>		Plan Type/Shape: <b>Rectangle</b>	Number of Stories: <b>1.0</b>
Foundation Material: <b>Concrete block</b>		Structural Framing: <b>Unknown</b>	Moved? <b>No</b>
Roof Type/Material: <b>Gable / Composition shingle</b>		Window Type/Material: <b>Vinyl sliders; aluminum fixed</b>	
Exterior Surface Materials Primary: <b>Vertical T&amp;G</b>		Secondary: <b>Lap</b>	Decorative:
Exterior Alterations or Additions/Approximate Date: <b>Boxed soffits; metal columns &amp; Roman brick on porch; new front door</b>			
Number and Type of Associated Resources: <b>None</b>			
Integrity: <b>Poor</b>		Condition: <b>Good</b>	Local Ranking:
			National Register Listed? <b>No</b>
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Not 50 years old <input checked="" type="checkbox"/> Irretrievable loss of integrity			
Description of Physical and Landscape Features:			
This one story bungalow has a rectangular plan and sits on a poured concrete foundation. The gable roof is covered in composition shingles and the eaves are supported by decorative brackets. The gables are sheathed in lap siding. The walls are covered with vertical tongue and groove siding. Windows are primarily sliders. The main window on the front façade are three narrow fixed panes. The large porch is covered with a gable roof that is supported by metal columns with Roman brick rail.			
Statement of Significance:			
Researcher/Organization: <b>Heather Goodson / HPNW</b>			Date Recorded: <b>5/10/2002</b>
<b>Survey Form Page 1</b>	Address: <b>104 HIGH ST</b>	Local Designation #	SHPO #