

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 504 JACKSON ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 08 N	Longitude: 122 36 04 W
Township: 02S	Range: 02E	Section: 31 Block: 163 Lot: 5x, 4	Map #: 22E31DA Tax Lot #: 1100
Date of Construction: c. 1930	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Bungalow		Plan Type/Shape: Square	Number of Stories: 1.5
Foundation Material: Concrete		Structural Framing: Unknown	Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: 1/1 wood double-hung; large picture fixed	
Exterior Surface Materials Primary: Asbestos shingle		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: Carpport, brick stairway, probably entry porch enclosure; asbestos shingle siding.			
Number and Type of Associated Resources: None			
Integrity: Poor Condition: Poor		Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Not 50 years old <input checked="" type="checkbox"/> Irretrievable loss of integrity			
Description of Physical and Landscape Features:			
This much-altered c.1930 bungalow includes shed dormers on the east and west elevations, wide barge boards, exposed rafter tails, and knee brackets. Brick veneer has been applied to the lower half of the house. The east façade features a newer porch overhang. The windows are primarily aluminum with storm windows. There is a carpport on the north side addition, and a brick exterior chimney on the south.			
Statement of Significance:			

Researcher/Organization: Marti Gerdes / HPNW		Date Recorded: 5/11/2002	
Survey Form Page 1	Address: 504 JACKSON ST	Local Designation #	SHPO #