

### OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: <b>522 JACKSON ST</b>		City: <b>OREGON CITY</b>	
USGS Quad Name: <b>Oregon City</b>		GPS Latitude: <b>45 21 10 N</b>	Longitude: <b>122 36 02 W</b>
Township: <b>02S</b>	Range: <b>02E</b>	Section: <b>31</b> Block: <b>163</b> Lot: <b>7, 8</b>	Map #: <b>22E31DA</b> Tax Lot #: <b>1300</b>
Date of Construction: <b>c. 1925</b>	Historic Name:	Historic Use or Function: <b>Domestic - single dwelling</b>	
Grouping or Cluster Name: <b>NA</b>	*Current Name or Use: <b>Domestic - single dwelling</b>	Associated Archaeological Site: <b>Unknown</b>	
Architectural Classification(s): <b>Bungalow</b>		Plan Type/Shape: <b>Rectangle</b>	Number of Stories: <b>1.0</b>
Foundation Material: <b>Concrete</b>		Structural Framing: <b>Unknown</b>	Moved? <b>No</b>
Roof Type/Material: <b>Gable / Composition shingle</b>		Window Type/Material: <b>1/1 wood double-hung</b>	
Exterior Surface Materials Primary: <b>Round-edge drop</b>		Secondary: <b>Wood shingle</b>	Decorative:
Exterior Alterations or Additions/Approximate Date: <b>Attached garage possibly 1930s; removed south wall above garage</b>			
Number and Type of Associated Resources: <b>None</b>			
Integrity: <b>Good</b> Condition: <b>Good</b>		Local Ranking:	National Register Listed? <b>No</b>
Potentially Eligible: <input type="checkbox"/> Individually or <input checked="" type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
A shed roofed-porch with tapered boxed columns and a knee wall distinguish this rectangular bungalow c.1925. The roof subsheathing of plywood and the narrow barge boards indicate a replacement roof. The windows, except one (a rear bathroom vinyl window), appear to be original 1/1 wood double-hung with lamb's tongues. There is shingle siding in the gable. A full basement features an add-on room (possibly a garage originally) with a flat roof. Sliding 2/2 windows pierce the walls at basement level on the street elevation. A sliding glass door leads from the rear into the canyon-like back yard.			
Statement of Significance:			

Researcher/Organization: <b>Marti Gerdes / HPNW</b>		Date Recorded: <b>4/6/2002</b>	
<b>Survey Form Page 1</b>	Address: <b>522 JACKSON ST</b>	Local Designation #	SHPO #