

OREGON CITY HISTORIC RESOURCE SURVEY FORM

| | | | |
|---|--|--|-------------------------------|
| Street Address: 601-611 JACKSON ST | | City: OREGON CITY | |
| USGS Quad Name: Oregon City | | GPS Latitude: 45 21 12 N | Longitude: 122 36 02 W |
| Township: 02S | Range: 02E | Section: 31 | Block: 158 |
| Lot: 3x, 4x | | Map #: 22E31AD | Tax Lot #: 7900 |
| Date of Construction: c. 1930 | Historic Name: | Historic Use or Function: Domestic - single dwelling | |
| Grouping or Cluster Name: NA | *Current Name or Use: Domestic - multiple dwelling | Associated Archaeological Site: Unknown | |
| Architectural Classification(s): Minimal Traditional | | Plan Type/Shape: Complex | Number of Stories: 1.5 |
| Foundation Material: Concrete | | Structural Framing: Unknown | Moved? No |
| Roof Type/Material: Gable / Composition shingle | | Window Type/Material: 1/1 vinyl; casement | |
| Exterior Surface Materials Primary: Wood shingle | | Secondary: | Decorative: |
| Exterior Alterations or Additions/Approximate Date: Vestiges of larger window, door openings indicate far different configuration. | | | |
| Number and Type of Associated Resources: None | | | |
| Integrity: Good | | Condition: Excellent | Local Ranking: |
| | | National Register Listed? No | |
| Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input checked="" type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old | |  | |
| Description of Physical and Landscape Features: | | | |
| This complex-shaped building c.1930 houses six apartments with entrances off both Jackson and an alley. The roof features gables on multiple sides, prominent knee brackets, boxed eaves, multiple stoops and wrought-iron railings. The siding is wood shingle, and vestiges of larger window and door openings indicate a far different configuration originally. The windows are 1/1 vinyls and a few casements. | | | |
| Statement of Significance: | | | |
| | | | |

| | | | |
|---|------------------------------------|---------------------------------|--------|
| Researcher/Organization: Marti Gerdes / HPNW | | Date Recorded: 5/11/2002 | |
| Survey Form Page 1 | Address: 601-611 JACKSON ST | Local Designation # | SHPO # |