

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 802 JACKSON ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 16 N	Longitude: 122 35 56 W
Township: 02S	Range: 02E	Section: 32	Block: 166 Lot: 5
Date of Construction: c. 1925		Historic Name:	Historic Use or Function: Domestic - single dwelling
Grouping or Cluster Name: NA		*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown
Architectural Classification(s): Bungalow		Plan Type/Shape: Square	Number of Stories: 1.5
Foundation Material: Concrete		Structural Framing: Unknown	Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: 4/1 wood double-hung	
Exterior Surface Materials Primary: Lap		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: Metal hand rail.			
Number and Type of Associated Resources: None			
Integrity: Excellent		Condition: Excellent	Local Ranking:
			National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input checked="" type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This c.1925 Craftsman bungalow is side-gabled resting on a concrete foundation. It features a shed dormer over the entry with aluminum storm windows. Notched rafter tails are character-defining features; other details include eave brackets, knee railing, and tapered boxed porch columns. The entry door is highlighted by a 3-pane panel with modillions. The full-length porch features 3-panel windows of vertical 2/1 double-hung design, flanking a vertical 3/1 central panel window. The porch is T&G. The chimney pierces the roof at the eave, and aluminum windows are on the side elevation at the rear. There is a brick chimney on the south elevation.			
Statement of Significance:			

Researcher/Organization: Marti Gerdes / HPNW		Date Recorded: 5/11/2002	
Survey Form Page 1	Address: 802 JACKSON ST	Local Designation #	SHPO #