

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 805 JACKSON ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 17 N	Longitude: 122 35 57 W
Township: 02S	Range: 02E	Section: 32 Block: 156 Lot: 4	Map #: 22E32BC Tax Lot #: 7300
Date of Construction: 1938	Historic Name:	Historic Use or Function: Religion - church hall	
Grouping or Cluster Name: NA	*Current Name or Use: Bible Doctrine Church	Associated Archaeological Site: Unknown	
Architectural Classification(s): Minimal Traditional		Plan Type/Shape: Square	Number of Stories: 1.0
Foundation Material: Concrete		Structural Framing: Unknown	Moved? No
Roof Type/Material: Gabe / Composition shingle		Window Type/Material: 1/1 stained glass with elliptical arch	
Exterior Surface Materials Primary: Wood shingle		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: Entry is likely an alteration. Handicap ramp.			
Number and Type of Associated Resources: None			
Integrity: Good	Condition: Good	Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input checked="" type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This eaveless, gable-front church built in 1938 features a gable over the entry porch. The main elevation is distinguished by a centered, large arched stained glass window with Plexiglas storm windows (screwed on), flanked by smaller windows similar in design. A concrete universal access ramp extends across 3/4 of the front façade. There is a basement. The construction date is stamped on the steps. The porch ceiling is beadboard and is supported by solid columns. There is a louvered vent in the gable and wood shingle siding.			
Statement of Significance:			
Researcher/Organization: Marti Gerdes / HPNW			Date Recorded: 5/11/2002
Survey Form Page 1	Address: 805 JACKSON ST	Local Designation #	SHPO #