

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 813 JACKSON ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 18 N	Longitude: 122 35 56 W
Township: 02S	Range: 02E	Section: 32 Block: 156 Lot: 2x	Map #: 22E32BC Tax Lot #: 6700
Date of Construction: c. 1910	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Bungalow		Plan Type/Shape: Square	Number of Stories: 1.5
Foundation Material: Concrete		Structural Framing: Unknown	Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: 1/1 wood double-hung	
Exterior Surface Materials Primary: Round-edge drop		Secondary: Wood shingle	Decorative:
Exterior Alterations or Additions/Approximate Date: Window on south at rear is larger than would be customary for this time period. Weather enclosures at entries.			
Number and Type of Associated Resources: Period garage at rear (1)			
Integrity: Good Condition: Good		Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input checked="" type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This 1-1/2 story, c.1910 bungalow features wide barge boards with subtly decorated eave brackets and barge board tails. The front gabled elevation is highlighted by paired 1/1 windows with leaded details in the upper sash; the remainder of the house includes 1/1 plain wood double-hung windows. The door and window surrounds are capped with minimally decorated hoods. Both front and rear entries feature recessed enclosures on the weather side with a glass and wood panel. A slightly projecting room with paired windows distinguishes the south elevation. A window on the south at the rear of the house appears larger than would be customary for this time period, indicating it is a replacement. A period garage sits to the rear of the house.			
Statement of Significance:			
Researcher/Organization: Marti Gerdes / HPNW			Date Recorded: 5/11/2002
Survey Form Page 1	Address: 813 JACKSON ST	Local Designation #	SHPO #