

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 815 JACKSON ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 18 N	Longitude: 122 35 55 W
Township: 02S	Range: 02E	Section: 32	Block: 156 Lot: 2x
Date of Construction: c. 1915	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Bungalow		Plan Type/Shape: Rectangle	Number of Stories: 1.5
Foundation Material: Unknown		Structural Framing: Unknown	Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: 1/1 wood double-hung	
Exterior Surface Materials Primary: Metal		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date:			
Number and Type of Associated Resources: None			
Integrity: Fair		Condition: Fair	Local Ranking:
			National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input checked="" type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This 1-1/2 story, vernacular gable-end house c.1915 includes wide barge boards with minimally decorated rafter tail ends. Eave brackets are present. The soffits and porch ceiling appear to be original bead board. The trim around the door and windows has been removed to accommodate the metal siding. The porch floor appears to be original T&G. Boxed columns flank the porch entry at the main doorway. The windows are 1/1 wood double-hung. The gables feature board and batten construction and a shed dormer distinguishes the north elevation. There is an inset corner entry with an attractive entry door.			
Statement of Significance:			

Researcher/Organization: Marti Gerdes / HPNW		Date Recorded: 5/11/2002	
Survey Form Page 1	Address: 815 JACKSON ST	Local Designation #	SHPO #