

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 110 JEFFERSON ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 05 N	Longitude: 122 36 27 W
Township: 02S	Range: 02E	Section: 31	Block: 13 Lot: 1
Date of Construction: c. 1910	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	

Architectural Classification(s): Vernacular	Plan Type/Shape: Rectangle	Number of Stories: 2.0
Foundation Material: Concrete block	Structural Framing: Unknown	Moved? Yes
Roof Type/Material: Gable / Composition shingle	Window Type/Material: 8-pane fixed; 1/1 and 6/6 wood double-hung	
Exterior Surface Materials Primary: Channel drop	Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: Corner porch enclosed; gable addition to south; gable addition to north; upper front windows missing - storms remain; decorative shutters added; entry deck to south		
Number and Type of Associated Resources: Garage along sidewalk and shed to rear (2)		

Integrity: Fair	Condition: Good	Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input checked="" type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			

Description of Physical and Landscape Features:

This two story vernacular residence has a rectangular plan with a gabled addition to both the north and south sides. It sits on a concrete block foundation and is clad in channel drop siding with corner boards. The front gabled roof is covered with composition shingling. The windows are primarily 6/6 wooden double-hung. The front elevation has an 8-pane fixed window. The upper front windows are missing with only the storms in their place. Decorative shutters have been added. The corner front porch has been enclosed. There is a south side entry deck to the south facing front door. There is a rear chimney and a basalt retaining wall in the front yard.

Associated structures include a 2000 shed in back and a 1950s plywood formed concrete garage located at the sidewalk on the south property line.

Statement of Significance:

Researcher/Organization: Carin Petersen / HPNW	Date Recorded: 5/11/2002
Survey Form Page 1	Address: 110 JEFFERSON ST Local Designation # SHPO #