

## OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: <b>124 JEFFERSON ST</b>		City: <b>OREGON CITY</b>	
USGS Quad Name: <b>Oregon City</b>		GPS Latitude: <b>45 21 06 N</b>	Longitude: <b>122 36 25 W</b>
Township: <b>02S</b>	Range: <b>02E</b>	Section: <b>31</b> Block: <b>13</b> Lot: <b>4</b>	Map #: <b>22E31DB</b> Tax Lot #: <b>2300</b>
Date of Construction: <b>c. 1962</b>	Historic Name:	Historic Use or Function: <b>Domestic - single dwelling</b>	
Grouping or Cluster Name: <b>NA</b>	*Current Name or Use: <b>Domestic - single dwelling</b>	Associated Archaeological Site: <b>Unknown</b>	
Architectural Classification(s): <b>Minimal Tract</b>		Plan Type/Shape: <b>Rectangle</b>	Number of Stories: <b>1.0</b>
Foundation Material: <b>Concrete block</b>		Structural Framing: <b>Unknown</b>	Moved? <b>No</b>
Roof Type/Material: <b>Gable / Composition shingle</b>		Window Type/Material: <b>Aluminum sliders; aluminum fixed</b>	
Exterior Surface Materials Primary: <b>Vertical groove plywo</b>		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: <b>Full siding replacement</b>			
Number and Type of Associated Resources: <b>Garage at street level (1)</b>			
Integrity: <b>Fair</b>	Condition: <b>Good</b>	Local Ranking:	National Register Listed? <b>No</b>
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input checked="" type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This single story residence has a rectangular plan. It sits on a concrete block foundation and is clad in vertical groove plywood siding. The low sloped front gable has large overhangs with brackets and is covered in composition shingling. The windows are primarily aluminum sliding or fixed. There is a low chimney on the north side. The site is landscaped with numerous basalt retaining walls through which a concrete stair makes its way to the front door.  The detached garage is at street level with a gabled roof.			
Statement of Significance:			
Researcher/Organization: <b>Carin Petersen / HPNW</b>			Date Recorded: <b>5/11/2002</b>
<b>Survey Form Page 1</b>	Address: <b>124 JEFFERSON ST</b>	Local Designation #	SHPO #