

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 804 JEFFERSON ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 23 N	Longitude: 122 36 08 W
Township: 02S	Range: 02E	Section: 31 Block: 113 Lot: 5	Map #: 22E31AD Tax Lot #: 3100
Date of Construction: 1943	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Minimal Tract		Plan Type/Shape: Rectangle	Number of Stories: 1.5
Foundation Material: Concrete		Structural Framing: Unknown	Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: 1/1 double-hung wood and fixed windows	
Exterior Surface Materials Primary: Lap		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: None apparent			
Number and Type of Associated Resources: None			
Integrity: Excellent Condition: Excellent		Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input checked="" type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This 1-1/2 story house has a front gable and poured concrete foundation. There is a front gabled brick entrance with an arched door projecting from the front elevation. The porch has glass block side windows. There is decorative rake board with flared edges. The fixed picture windows flank the porch entrance. A pair of one over one double-hung wood windows are centered directly above the porch gable. Two gable dormers with decorative rake boards peek out from the north roof elevation. The north elevation also has an exterior chimney the width of a fireplace. North and south side windows have horizontal muntins. The southeast corner has a corner window. The attached garage at the back of the house has the matching rake board and a back door entrance. Double garage doors face south and a pair of double-hung windows in the garage face east. Picket fence surrounds the yard. There is a large tree in SW corner.			
Statement of Significance:			
Researcher/Organization: Rebecca Nielsen / HPNW			Date Recorded: 5/10/2002
Survey Form Page 1	Address: 804 JEFFERSON ST	Local Designation #	SHPO #