

## OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: <b>906 JEFFERSON ST</b>		City: <b>OREGON CITY</b>	
USGS Quad Name: <b>Oregon City</b>		GPS Latitude: <b>45 21 26 N</b>	Longitude: <b>122 36 05 W</b>
Township: <b>02S</b>	Range: <b>02E</b>	Section: <b>31</b> Block: <b>114</b> Lot: <b>6, 5x</b>	Map #: <b>22E31AA</b> Tax Lot #: <b>8400</b>
Date of Construction: <b>c. 1935</b>	Historic Name:	Historic Use or Function: <b>Domestic - single dwelling</b>	
Grouping or Cluster Name: <b>NA</b>	*Current Name or Use: <b>Domestic - single dwelling</b>	Associated Archaeological Site: <b>Unknown</b>	
Architectural Classification(s): <b>Minimal Traditional</b>		Plan Type/Shape: <b>Rectangle</b>	Number of Stories: <b>1.0</b>
Foundation Material: <b>Concrete</b>		Structural Framing: <b>Unknown</b>	Moved? <b>No</b>
Roof Type/Material: <b>Jerkinhead / Composition shingle</b>		Window Type/Material: <b>1/1 aluminum; large picture</b>	
Exterior Surface Materials Primary: <b>Vinyl</b>		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: <b>Non-historic porch enclosure</b>			
Number and Type of Associated Resources: <b>None</b>			
Integrity: <b>Poor</b>	Condition: <b>Excellent</b>	Local Ranking:	National Register Listed? <b>No</b>
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Not 50 years old <input checked="" type="checkbox"/> Irretrievable loss of integrity			
Description of Physical and Landscape Features:			
This c.1935 minimal traditional house is rectangular in plan with a jerkinhead roof. A hip roof is present over an enclosed porch entrance. Classical elements, such as applied flat pilasters surround the recessed entrance door. The windows are 1/1 aluminum frame typically, with a fixed picture window at the front elevation. The exterior is clad in vinyl siding. Concrete steps lead up to the entrance porch, which has a metal hand railing. A concrete retaining wall encircles the property on the north and east elevations. Established trees and shrubs are present in the front yard.			
Statement of Significance:			

Researcher/Organization: <b>Christy Fockler / HPNW</b>		Date Recorded: <b>4/12/2002</b>	
<b>Survey Form Page 1</b>	Address: <b>906 JEFFERSON ST</b>	Local Designation #	SHPO #