

## OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: <b>1102 JEFFERSON ST</b>		City: <b>OREGON CITY</b>	
USGS Quad Name: <b>Oregon City</b>		GPS Latitude: <b>45 21 30 N</b>	Longitude: <b>122 36 01 W</b>
Township: <b>02S</b>	Range: <b>02E</b>	Section: <b>31</b> Block: <b>116</b> Lot: <b>5</b>	Map #: <b>22E31AA</b> Tax Lot #: <b>600</b>
Date of Construction: <b>c. 1920</b>	Historic Name:	Historic Use or Function: <b>Domestic - single dwelling</b>	
Grouping or Cluster Name: <b>NA</b>	*Current Name or Use: <b>Domestic - single dwelling</b>	Associated Archaeological Site: <b>Unknown</b>	
Architectural Classification(s): <b>Craftsman</b>		Plan Type/Shape: <b>Square</b>	Number of Stories: <b>1.5</b>
Foundation Material: <b>Concrete</b>		Structural Framing: <b>Unknown</b>	Moved? <b>No</b>
Roof Type/Material: <b>Cross gable / Composition shingle</b>		Window Type/Material: <b>1/1 wood double-hung</b>	
Exterior Surface Materials Primary: <b>Vinyl</b>		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: <b>Full siding replacement, porch columns and shutters</b>			
Number and Type of Associated Resources: <b>None</b>			
Integrity: <b>Fair</b> Condition: <b>Good</b>		Local Ranking:	National Register Listed? <b>No</b>
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input checked="" type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
The 1-1/2 story former Craftsman style house has wide boxed eaves, brackets on all gables, boxed soffit, and a barge board that flares at the ends. There is a bank of four windows over a full-width porch. Windows have metal storms over original wood windows underneath with wavy glass and lamb's tongue detailing, 1/1 double-hung. Most windows have decorative shutters. Metal open-work supports have replaced original porch supports. The main front elevation window looks out over porch. It consists of one fixed picture window with a single horizontal muntin in the top third flanked by a 1/2 double-hung window on either side. Six wood steps lead up to the porch on the south side of the west elevation. The porch has T&G decking. A three-sided box bay on the south side with shed roof has one set of paired double-hung windows. The basement has slider metal windows on the south side. The east elevation has narrow one over one windows on the ground floor and one large metal slider window cut into the second story.			
Statement of Significance:			
Researcher/Organization: <b>Rebecca Nielsen / HPNW</b>			Date Recorded: <b>5/10/2002</b>
<b>Survey Form Page 1</b>	Address: <b>1102 JEFFERSON ST</b>	Local Designation #	SHPO #