

### OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: <b>104 JOHN ADAMS ST</b>		City: <b>OREGON CITY</b>	
USGS Quad Name: <b>Oregon City</b>		GPS Latitude: <b>45 21 06 N</b>	Longitude: <b>122 36 30 W</b>
Township: <b>02S</b>	Range: <b>02E</b>	Section: <b>31</b> Block: <b>135</b> Lot: <b>5</b>	Map #: <b>22E31DB</b> Tax Lot #: <b>6800</b>
Date of Construction: <b>c. 1942</b>	Historic Name:	Historic Use or Function: <b>Domestic - single dwelling</b>	
Grouping or Cluster Name: <b>NA</b>	*Current Name or Use: <b>Domestic - single dwelling</b>	Associated Archaeological Site: <b>Unknown</b>	
Architectural Classification(s): <b>Minimal Traditional</b>		Plan Type/Shape: <b>Square</b>	Number of Stories: <b>1.0</b>
Foundation Material: <b>Unknown</b>		Structural Framing: <b>Unknown</b>	Moved? <b>No</b>
Roof Type/Material: <b>Gable / Composition shingle</b>		Window Type/Material: <b>Fixed aluminum sliders</b>	
Exterior Surface Materials Primary: <b>Stucco</b>		Secondary: <b>Lap</b>	Decorative:
Exterior Alterations or Additions/Approximate Date: <b>2 additions in back; windows, stucco</b>			
Number and Type of Associated Resources: <b>None</b>			
Integrity: <b>Fair</b> Condition: <b>Good</b>		Local Ranking:	National Register Listed? <b>No</b>
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Not 50 years old <input checked="" type="checkbox"/> Irretrievable loss of integrity			
Description of Physical and Landscape Features:			
This side gabled minimal traditional has a front gable entry vestibule. The foundation is not visible from the public right of way. The house features horizontal lap siding in the gables and stucco below. All of the windows appear to be changed to metal windows. There is round metal chimney. There appears to be two additions on the eastern elevation which is the back of the house. One has a shed roof and one has a gable roof.			
Statement of Significance:			

Researcher/Organization: <b>Rebecca Nielsen / HPNW</b>		Date Recorded: <b>4/12/2002</b>	
<b>Survey Form Page 1</b>	Address: <b>104 JOHN ADAMS ST</b>	Local Designation #	SHPO #