

## OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: <b>108 JOHN ADAMS ST</b>		City: <b>OREGON CITY</b>	
USGS Quad Name: <b>Oregon City</b>		GPS Latitude: <b>45 21 06 N</b>	Longitude: <b>122 36 29 W</b>
Township: <b>02S</b>	Range: <b>02E</b>	Section: <b>31</b> Block: <b>135</b> Lot: <b>6</b>	Map #: <b>22E31DB</b> Tax Lot #: <b>6900</b>
Date of Construction: <b>c. 1945</b>	Historic Name:	Historic Use or Function: <b>Domestic - single dwelling</b>	
Grouping or Cluster Name: <b>NA</b>	*Current Name or Use: <b>Domestic - single dwelling</b>	Associated Archaeological Site: <b>Unknown</b>	
Architectural Classification(s): <b>Minimal Tract</b>		Plan Type/Shape: <b>Square</b>	Number of Stories: <b>1.0</b>
Foundation Material: <b>Concrete block</b>		Structural Framing: <b>Unknown</b>	Moved? <b>No</b>
Roof Type/Material: <b>Gable / Composition shingle</b>		Window Type/Material: <b>Aluminum fixed; aluminum sliders</b>	
Exterior Surface Materials Primary: <b>Vertical groove plywo</b>		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: <b>Partial window replacement; front deck addition; rear shed addition</b>			
Number and Type of Associated Resources: <b>None</b>			
Integrity: <b>Poor</b> Condition: <b>Fair</b>		Local Ranking:	National Register Listed? <b>No</b>
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Not 50 years old <input checked="" type="checkbox"/> Irretrievable loss of integrity			
Description of Physical and Landscape Features:			
This simple c.1945 house is square in plan with a side facing gable roof. A small front facing gable roof projects out over an enclosed entry porch. The exterior is clad in painted vertical groove plywood with horizontal lap siding in the gable ends of the roof. The windows are aluminum fixed and sliders with varying sizes and configurations. Alterations include a newly remodeled wood deck and stair addition at the main entry and a rear shed addition.			
Statement of Significance:			

Researcher/Organization: <b>Christy Fockler / HPNW</b>		Date Recorded: <b>4/12/2002</b>	
<b>Survey Form Page 1</b>	Address: <b>108 JOHN ADAMS ST</b>	Local Designation #	SHPO #