

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 208 JOHN ADAMS ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 08 N	Longitude: 122 36 27 W
Township: 02S	Range: 02E	Section: 31 Block: 106 Lot: 6, 5x	Map #: 22E31DB Tax Lot #: 4000
Date of Construction: c. 1932	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Bungalow		Plan Type/Shape: Square	Number of Stories: 1.0
Foundation Material: Unknown		Structural Framing: Unknown	Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: 1/1 wood double-hung	
Exterior Surface Materials Primary: Wood shingle		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: Siding replacement			
Number and Type of Associated Resources: None			
Integrity: Fair Condition: Fair		Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input checked="" type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This house sits high above the road and is accessible via a broken concrete stairway and path. The house and porch are front gabled. The porch is sided all around with the same non-original, large exposure shingles as the house. There is a small horizontal window on the south side of the porch. The roof has no eaves but a rake molding. Metal storms cover the west elevation window. No driveway is apparent from the road. The landscape is very rough with a lot of construction debris. It has several large pine trees in the yard and a fence on the south side.			
Statement of Significance:			
Researcher/Organization: Rebecca Nielsen / HPNW			Date Recorded: 4/12/2002
Survey Form Page 1	Address: 208 JOHN ADAMS ST	Local Designation #	SHPO #