

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 301 JOHN ADAMS ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 11 N	Longitude: 122 36 26 W
Township: 02S	Range: 02E	Section: 31 Block: 60 Lot: 4x	Map #: 22E31AC Tax Lot #: 9200
Date of Construction: c. 1900	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): No Style		Plan Type/Shape: Rectangle	Number of Stories: 1.5
Foundation Material: Concrete block		Structural Framing: Unknown	Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: 1/1 vinyl; fixed vinyl	
Exterior Surface Materials Primary: Asbestos shingle		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: Porch enclosure and rear addition			
Number and Type of Associated Resources: None			
Integrity: Poor Condition: Excellent		Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Not 50 years old <input checked="" type="checkbox"/> Irretrievable loss of integrity			
Description of Physical and Landscape Features:			
This c.1900 'no style' house is rectangular in plan with a steeply pitched side facing gable roof with a pent roof over a full width enclosed entry porch. A small shed roof projects over the main entrance door and is supported by 4x4 wood posts. Two fixed picture windows, both non-historic exist at the enclosed entry on two elevations. The typical window types are 1/1 and sliding non-historic vinyl windows. The exterior is clad with modern asbestos shingles. Alterations include the enclosure of an original entry porch and a detached carport addition.			
Statement of Significance:			
Researcher/Organization: Christy Fockler / HPNW			Date Recorded: 4/12/2002
Survey Form Page 1	Address: 301 JOHN ADAMS ST	Local Designation #	SHPO #