

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 106 S JOHN ADAMS ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 05 N	Longitude: 122 36 31 W
Township: 02S	Range: 02E	Section: 31	Block: NA Lot: NA Map #: 22E31DB Tax Lot #: 7400
Date of Construction: c. 1955	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Minimal Tract		Plan Type/Shape: Rectangle	Number of Stories: 1.0
Foundation Material: Concrete block		Structural Framing: Unknown	Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: 1/1 wood double-hung; fixed picture	
Exterior Surface Materials Primary: Lap		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: None apparent			
Number and Type of Associated Resources:			
Integrity: Good	Condition: Good	Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input checked="" type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This one story side-gable house sits on a concrete block foundation. Two front picture windows flank the front door which has a hip roof hood. Four wood steps with a metal rail lead up to the inset front door. Vertical siding surrounds the door inset in contrast to the lap siding of the rest of the house. A scalloped barge board made of vertical boards decorates the porch hood. Metal storm windows obscure the windows. A rock retaining wall edges the lawn as it sits approximately four feet above the road. Concrete steps cut through the retaining wall to lead to the house. A metal chimney punctuates the roof. A large fir tree grows in the center front lawn. Does not appear on the 1950 Sanborn map.			
Statement of Significance:			

Researcher/Organization: Rebecca Nielsen / HPNW		Date Recorded: 5/10/2002	
Survey Form Page 1	Address: 106 S JOHN ADAMS ST	Local Designation #	SHPO #