

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 719 JOHN ADAMS ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 24 N	Longitude: 122 36 14 W
Township: 02S	Range: 02E	Section: 31 Block: 64	Lot: 1x, 2x Map #: 22E31AA Tax Lot #: 13700
Date of Construction: c. 1910	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Vernacular		Plan Type/Shape: Rectangle	Number of Stories: 1.0
Foundation Material: Concrete block		Structural Framing: Unknown	Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: 1/1 double-hung wood	
Exterior Surface Materials Primary: Channel drop		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: Porch siding; front window, c.1940			
Number and Type of Associated Resources: None			
Integrity: Good Condition: Fair		Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input checked="" type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This one story front gabled house has a rake boards, corner boards and boxed soffits. There is also a water table and cap. A square three-sided bay with a hip roof projects from the south elevation. A small entrance porch is on the southeast corner of the house with corrugated metal board tacked on the south side of the once open side. The porch has a hip roof. The front window in the bay is a wide double-hung wood with a single horizontal muntin in the upper sash. The bay also has corner boards. The upper window is a fixed square. The north side has a double-hung 1/1 wood window with lamb's tongue detailing. The south elevation has another three-sided square bay with hip roof. A second front gable is recessed behind the first with a window squeezed between the gables at the roof angle. Basement windows are visible in the concrete block and have concrete sills.			
Statement of Significance:			
Researcher/Organization: Rebecca Nielsen / HPNW			Date Recorded: 5/10/2002
Survey Form Page 1	Address: 719 JOHN ADAMS ST	Local Designation #	SHPO #