

## OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: <b>805 JOHN ADAMS ST</b>		City: <b>OREGON CITY</b>	
USGS Quad Name: <b>Oregon City</b>		GPS Latitude: <b>45 21 25 N</b>	Longitude: <b>122 36 13 W</b>
Township: <b>02S</b>	Range: <b>02E</b>	Section: <b>31</b> Block: <b>65</b>	Lot: <b>3x, 4x</b> Map #: <b>22E31AA</b> Tax Lot #: <b>14500</b>
Date of Construction: <b>c. 1910</b>	Historic Name:	Historic Use or Function: <b>Domestic - single dwelling</b>	
Grouping or Cluster Name: <b>NA</b>	*Current Name or Use: <b>Domestic - single dwelling</b>	Associated Archaeological Site: <b>Unknown</b>	
Architectural Classification(s): <b>Vernacular</b>		Plan Type/Shape: <b>Rectangle</b>	Number of Stories: <b>1.0</b>
Foundation Material: <b>Concrete block</b>		Structural Framing: <b>Unknown</b>	Moved? <b>No</b>
Roof Type/Material: <b>Gable / Composition shingle</b>		Window Type/Material: <b>2/2 wood double-hung</b>	
Exterior Surface Materials Primary: <b>Asbestos shingle</b>		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: <b>Asbestos shingle siding; vinyl windows</b>			
Number and Type of Associated Resources: <b>Garage to SE (1)</b>			
Integrity: <b>Fair</b>	Condition: <b>Good</b>	Local Ranking:	National Register Listed? <b>No</b>
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Not 50 years old <input checked="" type="checkbox"/> Irretrievable loss of integrity			
Description of Physical and Landscape Features:			
This c.1910 vernacular residence is rectangular in plan with a front facing gabled roofline. A low-pitched hip roof is present above the main entrance door and is supported by 4x4 wood posts on two corners. The porch posts have a decorative chamfered edge detail and a side balustrade with decorative spindles. The windows are 2/2 wood double-hung with lamb's tongue detailing on the main elevation. Non-historic 1/1-vinyl windows exist on all other elevations. Alterations include a non-historic wood floor replacement at the entrance porch.  A garage exists to the south east of the house and is clad with asbestos shingle siding.			
Statement of Significance:			

Researcher/Organization: <b>Christy Fockler / HPNW</b>		Date Recorded: <b>4/12/2002</b>	
<b>Survey Form Page 1</b>	Address: <b>805 JOHN ADAMS ST</b>	Local Designation #	SHPO #