

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 811 JOHN ADAMS ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 26 N	Longitude: 122 36 12 W
Township: 02S	Range: 02E	Section: 31 Block: 65	Lot: 2x, 3x Map #: 22E31AA Tax Lot #: 14400
Date of Construction: c. 1935	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Minimal Traditional		Plan Type/Shape: Square	Number of Stories: 1.5
Foundation Material: Concrete		Structural Framing: Unknown	Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: Aluminum sliders	
Exterior Surface Materials Primary: Wood shingle		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: Window replacement; possible re-siding			
Number and Type of Associated Resources: None			
Integrity: Fair Condition: Good		Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Not 50 years old <input checked="" type="checkbox"/> Irretrievable loss of integrity			
Description of Physical and Landscape Features:			
This 1-1/2 Minimal Traditional has two eaveless front gables, the forward smaller gable projecting out from the larger recessed gable. Cornices extend out from the side elevations with boxed beadboard soffits. Windows are aluminum sliders and the exterior siding is wood shingle. An exterior chimney is located on the north elevation, while the south side boasts a shed roof dormer. A brick border runs from the watertable to the sidewalk of the east elevation, turning into a flowerbox under the front window which has a shed hood upheld by a small column in each corner. Basement windows are visible in the poured concrete foundation of the south elevation.			
Statement of Significance:			

Researcher/Organization: Rebecca Nielsen / HPNW		Date Recorded: 5/10/2002	
Survey Form Page 1	Address: 811 JOHN ADAMS ST	Local Designation #	SHPO #